

Pd: 15 — 100 M6ap BP			Pd: 100 — 300 M6ap MP			Pd: 300 — 3000 M6ap TR		
Pu M6ap	AC5	AC 1 O	Pu M6ap	AC5	AC 1 O	Pu M6ap	AC5	AC 1 O
Pd + 0,5 6ap	70	110	Pd + 0,5 6ap	70	110	Pd + 0,5 6ap	70	110
Pd + 1,0 6ap	160	170	Pd + 1,0 6ap	160	170	Pd + 1,0 6ap	160	170
Pd + 2,5 6ap	300	350	Pd + 2,5 6ap	300	350	Pd + 2,5 6ap	300	350
Pd + 5,0 6ap	200	250	Pd + 5,0 6ap	200	250	Pd + 5,0 6ap	200	250